

Due to possible bugs in FTDI drivers which may even lead to unexpected application hang and system crash it is strongly recommended to update drivers to version 2.8.14 or higher.

The procedure of updating drivers is following.

1. Download newest drivers from the Ober Consulting website
2. Unpack drivers to empty folder
3. Connect the system to the USB port
4. Open Device Manager
5. Navigate to „Universal Serial Bus controllers” branch
6. Right click on „Optical <-> USB” device
7. From the context menu choose “Update drivers...” option
8. In appropriate window choose to select drivers folder instead of having system to search from them
9. Selected downloaded drivers folder to be used when updating